Netherlands SACA

Ramp Inspection Report No. CAA-NL-2015-0195

| Source: | SACA | | Place: | EHKD - DEN HELDER/DE KOOY | |
|------------------------------------|-----------|------------------------------------|----------------------------|---|--|
| Date: | 15.06.201 | ō | Local Time: | 14:00 | |
| Operator: | 8AA | NOORDZEE HELIKOPTERS VLAANDEREN | AOC Number: | B-3037 | |
| State: | EB | Belgium | Type of Operation: | Commercial Air Transport operations (CAT) | |
| Route from: | NR | NOT RELEVANT | Flight Number: | NR | |
| Route to: | NR | NOT RELEVANT | Flight Number: | NR | |
| Chartered by | NR | NOT RELEVANT | Charterer's State: | Not Relevant | |
| Aircraft type: | AS65 | Eurocopter AS-365/565 Dauphin2 | Registration Marks: | OO-NHV | |
| Aircraft configuration: | Passenge | r 🤤 | Construction Number: | 6510 | |
| Flight Crew State of Licensing: | LF | France | 2nd State of Licensing*: | Netherlands | |

Findings

| Code | S | td | Ref | Cat | Finding | Detailed Description | Status | | | |
|---------------------------|-----------------------------|--|--|-----|---|---|--------|--|--|--|
| A14 | E | | CAT.POL.A.105 (a), CAT.POL.MAB.1 00 (a), CAT.POL.MAB.1 | 2 | Incorrect mass and/or balance calculations, within a/c limits, and having minor effect on the performance calculations. | Last weight report in tech log 2015, but info of 2014 used for weight and balance calculation | Open | | | |
| A23 | l | | | G | | Information about old deferred items in technical log, very confusing. | NR | | | |
| B05 | 1 | | | 3 | | Life raft stowed at passenger seat not secured. | Ореп | | | |
| C02 | N | 1 | mm 52 | 3 | | LH door (pilot) hold open rod not properly installed. | Open | | | |
| | Cla | NY TRAFT | tions taken | | Actions Taken | and the second second | | | | |
| | 3d) Immediate operating ban | | | | | | | | | |
| | | 3c) Aircraft grounded by inspecting NAA | | | | | | | | |
| | Ø | 3b) Co | rrective actions be | | | | | | | |
| | | 3a) Restriction on aircraft flight operation | | | | | | | | |
| | \checkmark | 2) information to Authority and Operator | | | | | | | | |
| 1) Information to Captain | | | | | | | | | | |
| | | | 1010.12.1 | | Additional Information | | | | | |

Special request for inspection, aircraft to be operated for SAR. Officially this operations in not performed under its AOC but under a contract with Rijkswaterstaat however the items checked during the Ramp Inspections are related to the CAT requirements and would also apply for CAT operations outside of the contract. Nevertheless this inspections should be seen as a special inspection and for which the BCAA is not the oversight authority in respect to the nature of the flight.

Report No CAA-NL-2015-0195

This report represents an indication of what was found on this occasion and must not be construed as a determination that the aircraft is fit for the intended flight